6. 3. Countrain a (way Asto/Escrucy)

stear Meante

R. M. Vining

R. W. Sterrett

H. A. Brown

R. dright ...

R. E. Schneider

C. R. Lowe (Zonolits/Atlanta) R. A. Kulbers

In connection with my schedule of supermicony safety training sessions at Keering and at Travelors Rest, the week of June 9, 2069, as you know, I conducted a safety survey or the Rearney expanding plant.

Although equipment and processes were noted to be properly safeguarded, dust in air and dust accumulations all horizontal surfaces was extremely heavy. Areas contributing to this contemnation include the Stoners, fines drop from vortex, a few small holes in the duct work and uncovered chutes at the bottoms of each of the furnace are elevators. Building vibration dislodged leage accumulations creating

It is probable that the dust collecting equipment here is adequate but that it needs to be checked out and tightened up. All recumplations should be cleaned up as soon as possible.

The pono-Kote mixing operation, also a source of durit (Toxic) contamination, should be equipped with local exhaust ventilation.